

## FEATURES

Ready for use, High Performance plastisol formulated for high speed automatic printing .  
Very creamy and short bodied, with low tack and for ease of printing, a greatly improved shear.  
Well suited for high definition and resolution, fine detail and halftone printing.  
Faster production speeds with less pressure. Can be printed through finer mesh counts for faster production speeds with less pressure .

## 7600 STOCK COLORS

7606 National Red	7623 Lemon Yellow	7673 Kelly Green
7607 HP Gldn Yellow	7624 Light Royal	7697 HP Gold
7608 Bear's Navy	7626 Bright Orange	
7610 Dark Navy	7628 S Drake Red	
7616 Graphics Purple	7630 Dark Gray	
7617 Baja Black	7646 Scarlet	
7618 Island Blue	7666 Royal Blue	
7620 Clck. Orange	7668 Navy Blue	

## Application & Storage Information

<b>RECOMMENDED FABRICS</b>	Light colored 100% cotton or cotton/polyester blends. Use an underbase for printing dark fabrics.
<b>INK APPLICATION</b>	Colors should be printed without any modifications. If thinning is required, use 10 99 LB Lo -Bleed Reducer (1% to 3% by weight).
<b>SCREEN MESH AND EMULSION</b>	110 to 305 t/in 43 to 120 t/cm Monofilament Any direct or indirect emulsion. Use 35 to 70 micron capillary film for best results.
<b>SQUEEGEE</b>	60-70 Durometer: Sharp Edge 60-90-60 or 70-90-70 Triple Durometer: Sharp Edge
<b>CURE TEMPERATURE</b>	325° (163°C) Entire ink film. Test dryer temperatures and wash test printed product before and during a production run.
<b>CLEAN -UP</b>	Any environmentally friendly plastisol screen wash .
<b>PRODUCT PACKAGING</b>	1 Gallon , 5 Gallon, or 30 Gallon Containers.
<b>STORAGE OF INK CONTAINERS</b>	Recommend storage at 65°F to 90°F (18°C to 32°C). Avoid storage in direct sunlight. Keep containers well sealed.
<b>PRODUCT MSDS</b>	Refer to material safety data sheet MSDS8.

## SPOT FLASHING

The 7600 inks will spot dry, with very low after flash tack, in 3 to 8 seconds depending on the spot dryer used. Too much heat / time may cause the ink to become sticky after flashing. Adjust flash unit accordingly. When spot drying, the ink should be just dry to the touch, with no lift off, but not totally fused. Totally fusing any of the flashed colors may cause inter -coat adhesion problems with the inks printed on top of the flashed ink. Final curing I fusing will occur in the dryer.

## IMPORTANT INFORMATION

1. Use an underbase print when printing 7600 inks onto dark fabrics. Use 7 11, 70 14 or 7031 white as an underbase ink. To achieve a softer hand and faster production speeds, print underbase ink through finer mesh counts 230 to 305 t/in or 90 to 120 t/cm.
2. The 7600 inks are low bleed inks, not non -bleed inks. On some types of fabric, bleeding or dye migration may occur. Always test print the fabric to be printed before beginning production. Bleeding or dye migration may not occur right away.
3. Excessive squeegee pressure will drive the 7600 inks through the fabric being printed. Adjust squeegee pressure, angle and off -contact to insure proper shear and lay down of printed ink. Proper settings of squeegee, flood bar and off -contact will improve performance, improve screen life and squeegee durability.
4. Adding too much reducer or other additives to the 7600 inks may cause curing/fusing or increased dye migration problems.
5. The 7600 inks are easy to print when compared to other inks and can be printed through finer mesh counts. This means less ink usage and faster production times, a real money saver. Using finer mesh counts also means a softer hand of the finished product .

Recommendations and statements made are based on International Coatings' research and experience. Since International Coatings does not have any control over the conditions of use or storage of the product sold, International Coatings cannot guarantee the results obtained through use of its products. All products are sold and samples given without any representation of warranty, expressed or implied, of fitness for any particular purpose or otherwise, and upon condition that the buyer shall determine the suitability of the product for its own purpose. This applies also where rights of third parties are involved. It does not release the user from the obligation to test the suitability of the product for the intended purpose and application.

7600 SERIES DIRECT PRINT PLASTISOL